



Note: Due to error in plan tie @ King Hill Rd. See recalculation of curves and tie Eny. #609 Calc. Bk #1C Pg 74. (7-19-77)

Note. Poles indicated thus: ●



Plan Bk 2 pl 112